


PK probes, EL pins, EG pins and screws  
to monitor moisture conditions with  
moisture meters, data loggers and wireless transmitters.



To connect EL and EG pins and stainless steel screws:

LP-H cable with loops and 4mm plugs connects to Ligno-VersaTec and Lignometer K via Adapter H.  
LP-Hf cable with loops and 4mm jacks connects to MC transmitter (transmitter wires have 4mm plugs).  
LP-mini-cable with loops and 2mm plugs connects to mini-Ligno DX/C, S/DC, MD/C and MC Tracker.

Loop nuts need to be ordered separately for EG and EL pins.

EL pins can be shortened to any length between 7" and 1/2" long.

To connect PK probes:

PK-H cable with 4mm plugs on both ends connects to Ligno-VersaTec and Lignometer K via Adapter H  
PK-mini cable with 4mm and 2mm plugs connects to mini-Ligno DX/C, S/DC, MD/C and MC Tracker.